

Focus Notes Standard Rig

Channel	Position	Fixture/s	Colour	Focus
1	FOH	S4 25-50 x 2		OP wash. Soft edge. Front of stage to cyc to pros. Avoid using top and side shutters
2	FOH	S4 25-50 x 2		C wash. Soft edge. Front of stage to cyc. Avoid using top and side shutters
3	FOH	S4 25-50 x 2		P wash. Soft edge. Front of stage to cyc to pros. Avoid using top and side shutters
4	FOH	Pac 23-50 x 2	L147	OP wash. Soft edge. Front of stage to cyc to pros. Avoid using top and side shutters
5	FOH	Pac 23-50 x 2	L147	C wash. Soft edge. Front of stage to cyc. Avoid using top and side shutters
6	FOH	Pac 23-50 x 2	L147	P wash. Soft edge. Front of stage to cyc to pros. Avoid using top and side shutters
7	FOH	S4 25-50 x 2	L079	OP wash. Soft edge. Front of stage to cyc to pros. Avoid using top and side shutters
8	FOH	S4 25-50 x 2	L079	C wash. Soft edge. Front of stage to cyc. Avoid using top and side shutters
9	FOH	S4 25-50 x 2	L079	P wash. Soft edge. Front of stage to cyc to pros. Avoid using top and side shutters
10	FOH	Sel 1200 Zoom x 2		Gobo wash OP-C. Sharp focus. Front of stage to cyc to pros
11	FOH	Sel 1200 Zoom x 2		Gobo wash P-C. Sharp focus. Front of stage to cyc to pros
12	FOH	Pac 12-28		OP d/s spec. Hard edge
13	FOH	Pac 12-28		C d/s spec. Hard edge
14	FOH	Pac 12-28		P d/s spec. Hard edge
15	FOH	Pac 12-28		C spec. Hard edge
16	FOH Boom	CCT Sil30 x 2	R119	OP wash. Front of stage to cyc. Shutter Pside lamp above head height along legs add frost R119
17	FOH Boom	CCT Sil30 x 2	R119	P wash. Front of stage to cyc. Shutter Oside lamp above head height along legs add frost R119
18	FOH Boom	CCT Sil30 x 2	R119	U/S cross wash. Can spill onto legs. Shutter above head height along cyc then add frost R119
19	FOH Boom	CCT Sil30 x 2		Cloud gobo wash on cyc. Sharp focus crossing centre. Can spill onto legs. Shutter off border
20	FOH Boom	Sparkler x 2		Full stage crossing centre. Off front of stage and pros
21	Truss	Par64 x 2	L170	C-P cross stage corridor just behind pros
22	Truss	Par64 x 2	L170	C-OP cross stage corridor just behind pros
23	Truss	Sel Rama x 2		C d/s wash. Almost full flood. To front edge of stage
24	Truss	Sel Rama x 2		OP + P d/s wash. Almost full flood. To front edge of stage .To pros
25	Line 4	Sel Compact x 2	L147	C d/s wash. Almost full flood. To front edge of stage
26	Line 4	Sel Compact x 2	L147	OP + P d/s wash. Almost full flood. To front edge of stage .To pros
27	Truss	Sel Rama x 2	L106	C d/s wash. Almost full flood. To front edge of stage
28	Truss	Sel Rama x 2	L106	OP + P d/s wash. Almost full flood. To front edge of stage .To pros
29	Line 4	CCT Starlette x 2	L079	C d/s wash. Almost full flood. To front edge of stage
30	Line 4	CCT Starlette x 2	L079	OP + P d/s wash. Almost full flood. To front edge of stage .To pros
31	Line 4	Pac 23-50 x 2		Gobo wash d/s. Sharp focus crossing centre. Can spill onto legs. Shutter front of stage
32	Line 13	Pac 23-50 x 2		Gobo wash u/s. Sharp focus crossing centre. Can spill onto legs. Shutter cyc
33	Line 15	S4 25-50 x 2		Special gobo wash c/s. Sharp focus crossing centre
34	Line 4	Sel 650 Zoom		Mid stage spec C-OP. Hard edge
35	Line 4	Sel 650 Zoom		Mid stage spec C-P. Hard edge
36	Line 13	Sel 650 Zoom		OP u/s spec. Hard edge
37	Line 13	Sel 650 Zoom		C u/s spec. Hard edge
38	Line 13	Sel 650 Zoom		P u/s spec. Hard edge
39	Line 13	Sel 650 Zoom		Random gobo onto cyc or u/s c special
40				
41	Line 13	CCT Starlette x 2		C u/s wash. Almost full flood. To bottom of cyc
42	Line 13	CCT Starlette x 2		OP + P u/s wash. Almost full flood. To bottom of cyc. To legs
43	Line 13	CCT Starlette x 2	L147	C u/s wash. Almost full flood. To bottom of cyc
44	Line 13	CCT Starlette x 2	L147	OP + P u/s wash. Almost full flood. To bottom of cyc. To legs
45	Line 13	CCT Starlette x 2	L106	C u/s wash. Almost full flood. To bottom of cyc
46	Line 13	CCT Starlette x 2	L106	OP + P u/s wash. Almost full flood. To bottom of cyc. To legs
47	Line 13	CCT Starlette x 2	L079	C u/s wash. Almost full flood. To bottom of cyc
48	Line 13	CCT Starlette x 2	L079	OP + P u/s wash. Almost full flood. To bottom of cyc. To legs
49	Floor	Footlight x 4		Footlight flood
50	Floor	Par64 x 2	quarter	Horizontal ceramic. D/S lamp centre of cyc to Pside. U/S lamp to Pside include stage apron
51	Floor	Par64 x 2	quarter	Horizontal ceramic. D/S lamp centre of cyc to Oside. U/S lamp to Oside include stage apron
52	FOH/ Line 4	UV x 2		UV wash
53	Line 15	3 way coda	L202	Backlight flood. Off cyc
54	Line 15	3 way coda	L202	Backlight flood. Off cyc
55	Line 15	3 way coda	L015	Backlight flood. Off cyc
56	Line 15	3 way coda	L015	Backlight flood. Off cyc
57	Line 15	3 way coda	L124	Backlight flood. Off cyc
58	Line 15	3 way coda	L124	Backlight flood. Off cyc
59	Line 15	Shimmer x 4		Backlight wash. Full width of stage to front edge of stage
60	Line 15	Derby x 2		45 degree wash across stage
61	Line 15	Par64 x 2	L180	Backlight wash OP. Ceramic u/s to d/s. Mid stage area to pros
62	Line 15	Par64 x 2	L180	Backlight wash OP-C. Ceramic u/s to d/s. Mid stage area to pros
63	Line 15	Par64 x 2	L180	Backlight wash P-C. Ceramic u/s to d/s. Mid stage area to pros
64	Line 15	Par64 x 2	L180	Backlight wash P. Ceramic u/s to d/s. Mid stage area to pros
65	FOH	S4 15-30		Spare special
66	FOH	Sel 1200 Zoom		Spare special
67	FOH	S4 15-30		Spare special
68	FOH	Sel 1200 Zoom		Spare special
69	FOH	S4 15-30		Spare special
70	Line 17	Sel PC		Centre backlight. Approx 5metres wide. Mid stage area
71	Line 17	Pac 12-28		Gobo rotator with glass gobo. Sharp focus. Diagonal splash across cyc OP to P
72	Line 17	Pac 12-28		Gobo rotator with glass gobo. Sharp focus. Diagonal splash across cyc P to OP

Focus Notes Standard Rig

Channel	Position	Fixture/s	Colour	Focus
73	Line8 Boom	Par64 x 2	L202	Horizontal ceramic. Cross stage wash. Centred on person centre stage in line with line 8
74	Line8 Boom	Par64 x 2	L202	Horizontal ceramic. Cross stage wash. Centred on person centre stage in line with line 8
75	Line8 Boom	Par64 x 2	L158	Horizontal ceramic. Cross stage wash. Centred on person centre stage in line with line 8
76	Line8 Boom	Par64 x 2	L158	Horizontal ceramic. Cross stage wash. Centred on person centre stage in line with line 8
77	Line8 Boom	Par64 x 2	L363	Horizontal ceramic. Cross stage wash. Centred on person centre stage in line with line 8
78	Line8 Boom	Par64 x 2	L363	Horizontal ceramic. Cross stage wash. Centred on person centre stage in line with line 8
79	Line8 Boom	Par64 x 2	L180	Horizontal ceramic. Cross stage wash. Centred on person centre stage in line with line 8
80	Line8 Boom	Par64 x 2	L180	Horizontal ceramic. Cross stage wash. Centred on person centre stage in line with line 8
81	Line 8	Mace x 2		Everywhere
82	Line 9	Sel PC x 2		Full spot onto mirror ball
83	Line 9	Mirror Ball		
84				
85	Line 10	Par64 x 4	L797	D/S backlight wash. Ceramic u/s to d/s
86	Line 10	Par64 x 4	L363	D/S backlight wash. Ceramic u/s to d/s
87	Line 10	Par64 x 4	L116	D/S backlight wash. Ceramic u/s to d/s
88				
89				
90				
91	Line 17	Sel Lui	L158	Cyc wash. Focussed off border
92	Line 17	Sel Lui	L026	Cyc wash. Focussed off border
93	Line 17	Sel Lui	L363	Cyc wash. Focussed off border
94	Line 17	Sel Lui	L124	Cyc wash. Focussed off border
95	Line 17	Gobo rotator	Glass	Slow speed
96	Line 17	Gobo rotator	Glass	Slow speed
97				
98				
99				
100				
101				
102				
103				
104				
105				
106				
107				
108				
109				
110				
111				
112				
113				
114				
115				
116				
117				
118				
119				
120				
121				
122				
123				
124				
125				
126				
127				
128	FOH Boom	CX-2 Dimmer		Cross wash onto cyc. Slight overlap at centre
129	FOH Boom	CX-2 Colour		
130	FOH Boom	CX-2 Gobo		
131	FOH Boom	CX-2 Speed		
132				